TNEMEC

Safety Data Sheet

Issue Date 13-Mar-2020 Revision Date 13-Mar-2020 Revision Number 7

1. IDENTIFICATION

Product identifier

Product Code N-69P020A

Product Name HB EPOXOLINEII BLACK-POOL

Other means of identification

Common Name SERIES N69/V69, PART A

UN/ID no. 1263 Synonyms None

Recommended use of the chemical and restrictions on use

Recommended Use industrial paint.

Uses advised againstConsumer use, For professional use only. Not for residential use.

Details of the supplier of the safety data sheet

Manufacturer Address Distributor

Tnemec Company, Inc. 6800 Corporate Drive, Kansas City, MO Tnemec Company, Inc. 86 Boul, des Entreprises, Ste. 203,

64120-1372 816-474-3400 Boisbriand, Quebec Canada J7G 2T3

Emergency telephone number

Company Phone Number Tnemec Regulatory Dept: 816-474-3400

24 Hour Emergency Phone Number 800-535-5053 (Infotrac)

2. HAZARDS IDENTIFICATION

Classification

OSHA Regulatory Status

This chemical is considered hazardous by the 2012 OSHA Hazard Communication Standard (29 CFR 1910.1200)

Acute toxicity - Oral	Category 4
Acute toxicity - Inhalation (Dusts/Mists)	Category 4
Skin corrosion/irritation	Category 2
Serious eye damage/eye irritation	Category 1
Skin sensitization	Category 1
Germ cell mutagenicity	Category 1B
Carcinogenicity	Category 1A
Reproductive Toxicity	Category 1B
Specific target organ toxicity (single exposure)	Category 3
Specific target organ toxicity (repeated exposure)	Category 1
Flammable Liquids	Category 3

Label elements

EMERGENCY OVERVIEW

Danger		
Hazard statements Causes skin irritation Causes serious eye damage May cause an allergic skin reaction May cause genetic defects		

May cause cancer

May damage fertility or the unborn child

May cause respiratory irritation. May cause drowsiness or dizziness

Causes damage to organs through prolonged or repeated exposure

Flammable liquid and vapor



Appearance opaque Physical state liquid Odor aromatic

Precautionary Statements

Prevention

Obtain special instructions before use

Do not handle until all safety precautions have been read and understood

Use personal protective equipment as required

Wash face, hands and any exposed skin thoroughly after handling

Do not eat, drink or smoke when using this product

Use only outdoors or in a well-ventilated area

Contaminated work clothing should not be allowed out of the workplace

Wear protective gloves

Do not breathe dust/fume/gas/mist/vapors/spray

Keep away from heat/sparks/open flames/hot surfaces. — No smoking

Keep container tightly closed

Ground/bond container and receiving equipment

Use only non-sparking tools

Take precautionary measures against static discharge

Use explosion-proof electrical/ventilating/lighting/mixing/equipment

Keep cool

Response

IF exposed or concerned: Get medical advice/attention

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing Immediately call a POISON CENTER or doctor/physician

If skin irritation or rash occurs: Get medical advice/attention

IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower

Wash contaminated clothing before reuse

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing

IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell

Rinse mouth

In case of fire: Use CO2, dry chemical, or foam for extinction

Storage

Store locked up

Store in a well-ventilated place. Keep container tightly closed

Keep away from children

Disposal

Dispose of contents/container to an approved waste disposal plant

Hazards not otherwise classified (HNOC)

If product is in liquid or paste form, physical or health hazards listed related to dust are not considered significant. However, product may contain substances that could be potential hazards if caused to become airborne due to grinding, sanding or other abrasive processes.

Other information

Harmful to aquatic life with long lasting effects

SEE SAFETY DATA SHEET

Acute Toxicity 8.75843 % of the mixture consists of ingredient(s) of unknown toxicity.

3. COMPOSITION/INFORMATION ON INGREDIENTS

Chemical name	CAS No.	Weight-%
BARIUM SULFATE (TOTAL DUST)	7727-43-7	10 - <30%
MAGNESIUM SILICATE	-	10 - <30%
XYLENE	1330-20-7	1 - <10%
BENZYL ALCOHOL	100-51-6	1 - <10%
MODIFIED CYCLOALIPHATIC POLYAMINE	68953-36-6	1 - <10%
N-BUTANOL (SKIN)	71-36-3	1 - <10%
ETHYL BENZENE	100-41-4	1 - <10%
ISOPHORONE DIAMINE	2855-13-2	1 - <10%
BENZENE, 1,3-DIMETHYL	108-38-3	0.1 - <1%

^{*}The exact percentage (concentration) of composition has been withheld as a trade secret.

4. FIRST AID MEASURES

Description of first aid measures

General advice If symptoms persist, call a physician.

Eye contact Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. Call

a physician immediately.

Skin contact Wash off immediately with soap and plenty of water while removing all contaminated

clothes and shoes. Consult a physician.

Inhalation If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is

difficult, give oxygen. Get medical attention immediately.

Ingestion If swallowed, do not induce vomiting. Get medical attention immediately.

Most important symptoms and effects, both acute and delayed

Notes to physician Treat symptomatically.

5. FIRE-FIGHTING MEASURES

Suitable extinguishing media

Carbon dioxide. Foam. Dry chemical.

Unsuitable extinguishing media Do not use a solid water stream as it may scatter and spread fire.

Specific hazards arising from the chemical

Thermal decomposition can lead to release of irritating gases and vapours In the event of fire and/or explosion do not breathe fumes

Hazardous combustion products Hazardous combustion products may include: A complex mixture of airborne solid and liquid particulates and gases (smoke). Carbon monoxide. Unidentified organic and inorganic compounds. Aldehydes. Carbon oxides. Hydrocarbons. Oxides of nitrogen.

Protective equipment and precautions for firefighters

Use water spray to cool unopened containers. In the event of fire, wear self-contained breathing apparatus. Keep away from

heat/sparks/open flames/hot surfaces. MAY CAUSE HEAT AND PRESSURE BUILD-UP IN CLOSED CONTAINERS. Solvent vapors are heavier than air and may spread along floors. Flash back possible over considerable distance.

6. ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

Personal precautions Avoid contact with eyes, skin and clothing. Use personal protective equipment. Remove all

sources of ignition. Ensure adequate ventilation.

Environmental Precautions

Environmental precautions Prevent further leakage or spillage if safe to do so. Do not flush into surface water or

sanitary sewer system.

Methods and material for containment and cleaning up

Methods for containment Remove all sources of ignition. Spills may be collected with inert, absorbent material for

proper disposal. Use non-sparking tools, protective gloves, goggles and clothing, adequate ventilation, avoid the breathing of vapors and use respiratory protective devices. Transfer

absorbent material to suitable containers for proper disposal.

Methods for cleaning up If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated

absorbent, container and unused contents in accordance with local, state and federal

regulations.

7. HANDLING AND STORAGE

Precautions for safe handling

Handling Close container after each use. Avoid contact with eyes, skin and clothing. Do not eat, drink

or smoke when using this product. If splashes are likely to occur, wear goggles. Wear protective gloves/clothing. Do not burn, or use a cutting torch on, the empty drum. When used in a mixture, read the labels and safety data sheets of all components. Wash

thoroughly after handling.

Conditions for safe storage, including any incompatibilities

Storage Keep container tightly closed in a dry and well-ventilated place. Keep out of the reach of

children.

Incompatible products Strong oxidizing agents. Acids. Bases. Cleaning solutions such as Chromerge and Aqua

Regia.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Control parameters

Exposure guidelines

Chemical name	ACGIH TLV	OSHA PEL	NIOSH IDLH
BARIUM SULFATE (TOTAL DUST) 7727-43-7	TWA: 5 mg/m³	TWA: 10 mg/m³ TWA: 5 mg/m³ TWA: 15 mg/m³	
MAGNESIUM SILICATE	TWA: 2 mg/m ³	TWA: 2 mg/m ³	1000 mg/m ³
XYLENE 1330-20-7	TWA: 100 ppm STEL: 150 ppm	TWA: 100 ppm TWA: 435 mg/m³ STEL: 150 ppm STEL: 655 mg/m³	
N-BUTANOL (SKIN)	TWA: 20 ppm	Skin	1400 ppm

71-36-3		Ceiling: 50 ppm Ceiling: 150 mg/m³ TWA: 100 ppm TWA: 300 mg/m³	
ETHYL BENZENE 100-41-4	TWA: 20 ppm	TWA: 100 ppm TWA: 435 mg/m³ STEL: 125 ppm STEL: 545 mg/m³	800 ppm
BENZENE, 1,3-DIMETHYL 108-38-3	TWA: 100 ppm STEL: 150 ppm	-	900 ppm

Appropriate engineering controls

Engineering measures Sufficient ventilation, in volume and pattern, should be provided through both local and

general exhaust to keep the air contaminant concentration below current applicable OSHA

Permissible Exposure Limits (PEL) and ACGIH's Threshold Limit Values (TLV).

Appropriate ventilation should be employed to remove hazardous decomposition products formed during welding or flame cutting operations of surfaces coated with this product.

Individual protection measures, such as personal protective equipment

Eye/face protectionUse chemical resistant splash type goggles. If splashes are likely to occur, wear

face-shield.

Skin and body protectionWear impervious protective clothing, including boots, gloves, lab coat, apron or coveralls,

as appropriate, to prevent skin contact.

Respiratory protectionUse only with adequate ventilation. Do not breathe vapors, spray mist, or dust. Ensure fresh

air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist or dust levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and

after application. Follow respirator manufacturer's directions for respirator use.

General hygiene considerations Handle in accordance with good industrial hygiene and safety practice.

Avoid breathing dust created by cutting, sanding, or grinding.

9. PHYSICAL AND CHEMICAL PROPERTIES

Information on basic physical and chemical properties

Physical state liquid

AppearanceopaqueOdoraromatic

ColorNo information availableOdor thresholdNo information available

<u>Property</u> <u>Values</u> <u>Remarks</u>

рΗ

Melting point / freezing point

No data available

Boiling point / boiling range

116 °C / 241.0 °F

Flash point 26 °C / 78.0 °F closed cup

Evaporation rate

Flammability (solid, gas) No data available

Flammability Limit in Air

Upper flammability limit 12.3 Lower flammability limit 1.5

Vapor pressure

Vapor density

Specific gravity 1.83011 g/cm3

Water solubility Insoluble in cold water

Solubility in other solvents

Partition coefficient: n-octanol/water

Autoignition temperature No data available Decomposition temperature No information available

Revision Date 13-Mar-2020

Kinematic viscosity No information available

Dynamic viscosity 1100 centipoises approx

Other Information

Molecular weightNo information availableDensity15.26308 lbs/galVolatile organic compounds (VOC)2.62678 lbs/gal

content

Total volatiles weight percent 17.21 % Total volatiles volume percent 36.69 %

Bulk density No information available

10. STABILITY AND REACTIVITY

Reactivity

No data available

Chemical stability

Stable under recommended storage conditions.

Possibility of hazardous reactions

None under normal processing.

Conditions to avoid

Heat, flames and sparks. Epoxy constituents.

Incompatible materials

Strong oxidizing agents, Acids, Bases, Cleaning solutions such as Chromerge and Aqua Regia

Hazardous decomposition products

Hazardous combustion products may include: A complex mixture of airborne solid and liquid particulates and gases (smoke). Carbon monoxide. Unidentified organic and inorganic compounds. Oxides of nitrogen. Aldehydes. Hydrocarbons. Carbon oxides.

11. TOXICOLOGICAL INFORMATION

Information on Likely Routes of Exposure

Inhalation Vapors may irritate throat and respiratory system. May cause central nervous system

depression with nausea, headache, dizziness, vomiting, and incoordination.

Eye contact Causes serious eye damage.

Skin contact Irritating to skin. May cause sensitization by skin contact.

Ingestion Harmful if swallowed.

Chemical name	LD50 Oral	LD50 Dermal	LC50 Inhalation
BARIUM SULFATE (TOTAL DUST)	= 307000 mg/kg (Rat)	-	-
7727-43-7			
XYLENE	= 3500 mg/kg (Rat)	> 1700 mg/kg (Rabbit) > 4350	= 29.08 mg/L (Rat) 4 h = 5000
1330-20-7		mg/kg (Rabbit)	ppm (Rat)4h
BENZYL ALCOHOL	= 1230 mg/kg (Rat)	= 2 g/kg (Rabbit)	= 8.8 mg/L (Rat) 4 h
100-51-6			
N-BUTANOL (SKIN)	= 700 mg/kg (Rat) = 790 mg/kg (= 3400 mg/kg (Rabbit) = 3402	> 8000 ppm (Rat) 4 h
71-36-3	Rat)	mg/kg (Rabbit)	
ETHYL BENZENE	= 3500 mg/kg (Rat)	= 15400 mg/kg (Rabbit)	= 17.4 mg/L (Rat) 4 h
100-41-4			
ISOPHORONE DIAMINE	= 1030 mg/kg (Rat)	> 2000 mg/kg (Rat)	-
2855-13-2			
BENZENE, 1,3-DIMETHYL	= 5 g/kg (Rat)	= 12.18 g/kg (Rabbit) = 14100	= 5984 ppm (Rat) 6 h
108-38-3		μL/kg (Rabbit)	

Information on toxicological effects

Symptoms Symptoms of overexposure may be headache, dizziness, tiredness, nausea and vomiting.

Skin disorders. Irritating to eyes and skin.

Delayed and immediate effects as well as chronic effects from short and long-term exposure

Skin corrosion/irritation Irritating to skin.

Eye damage/irritation Risk of serious damage to eyes.

Chronic Toxicity Skin sensitizer. Substances known to be mutagenic to man. Substances known to impair

fertility. May cause cancer. Avoid repeated exposure.

Sensitization May cause sensitization of susceptible persons.

Mutagenicity No information available.

Carcinogenicity The table below indicates whether each agency has listed any ingredient as a carcinogen.

Chemical name	ACGIH	IARC	NTP	OSHA
MAGNESIUM SILICATE		Group 3	-	
XYLENE 1330-20-7		Group 3	-	
ETHYL BENZENE 100-41-4	A3	Group 2B	-	X
BENZENE, 1,3-DIMETHYL 108-38-3		Group 3	-	

Reproductive effects
Suspected of damaging fertility or the unborn child.

STOT - single exposure Eyes, Central Nervous System (CNS), Skin

STOT - repeated exposure Causes damage to organs through prolonged or repeated exposure

Target organ effects blood, Central nervous system, Central Vascular System (CVS), Gastrointestinal tract,

Eyes, kidney, liver, Lungs, respiratory system, Skin.

Aspiration hazard No information available.

Acute Toxicity 8.75843 % of the mixture consists of ingredient(s) of unknown toxicity.

12. ECOLOGICAL INFORMATION

Ecotoxicity

Harmful to aquatic life with long lasting effects

12.66345557 % of the mixture consists of components(s) of unknown hazards to the aquatic environment

Chemical name	Toxicity to algae	Toxicity to fish	Toxicity to daphnia
MAGNESIUM SILICATE	-	100: 96 h Brachydanio rerio g/L	-
		LC50 semi-static	
XYLENE	-	LC50= 13.4 mg/L Pimephales	EC50 = 3.82 mg/L 48 h LC50 = 0.6
1330-20-7		promelas 96 h LC50 2.661 - 4.093	mg/L 48 h
		mg/L Oncorhynchus mykiss 96 h	_
		LC50 13.5 - 17.3 mg/L	
		Oncorhynchus mykiss 96 h LC50	
		13.1 - 16.5 mg/L Lepomis	
		macrochirus 96 h LC50= 19 mg/L	
		Lepomis macrochirus 96 h LC50	
		7.711 - 9.591 mg/L Lepomis	
		macrochirus 96 h LC50 23.53 -	
		29.97 mg/L Pimephales promelas	
		96 h LC50= 780 mg/L Cyprinus	
		carpio 96 h LC50> 780 mg/L	
		Cyprinus carpio 96 h LC50 30.26 -	
		40.75 mg/L Poecilia reticulata 96 h	
BENZYL ALCOHOL	35: 3 h Anabaena variabilis mg/L	460: 96 h Pimephales promelas	23: 48 h water flea mg/L EC50
100-51-6	EC50	mg/L LC50 static 10: 96 h Lepomis	
		macrochirus mg/L LC50 static	
N-BUTANOL (SKIN)	500: 72 h Desmodesmus	1740: 96 h Pimephales promelas	1983: 48 h Daphnia magna mg/L
71-36-3	subspicatus mg/L EC50 500: 96 h	mg/L LC50 flow-through 1730 -	EC50 1897 - 2072: 48 h Daphnia
	Desmodesmus subspicatus mg/L	1910: 96 h Pimephales promelas	magna mg/L EC50 Static
	EC50	mg/L LC50 static 1910000: 96 h	

		Pimephales promelas µg/L LC50 static 100000 - 500000: 96 h Lepomis macrochirus µg/L LC50 static	
ETHYL BENZENE 100-41-4	2.6 - 11.3: 72 h Pseudokirchneriella subcapitata mg/L EC50 static 4.6: 72 h Pseudokirchneriella subcapitata mg/L EC50 1.7 - 7.6: 96 h Pseudokirchneriella subcapitata mg/L EC50 static 438: 96 h Pseudokirchneriella subcapitata mg/L EC50	11.0 - 18.0: 96 h Oncorhynchus mykiss mg/L LC50 static 4.2: 96 h Oncorhynchus mykiss mg/L LC50 semi-static 7.55 - 11: 96 h Pimephales promelas mg/L LC50 flow-through 9.1 - 15.6: 96 h Pimephales promelas mg/L LC50 static 9.6: 96 h Poecilia reticulata mg/L LC50 static 32: 96 h Lepomis macrochirus mg/L LC50 static	1.8 - 2.4: 48 h Daphnia magna mg/L EC50
ISOPHORONE DIAMINE 2855-13-2	37: 72 h Desmodesmus subspicatus mg/L EC50	110: 96 h Leuciscus idus mg/L LC50 semi-static	42: 24 h Daphnia magna mg/L EC50 14.6 - 21.5: 48 h Daphnia magna mg/L EC50 semi-static
BENZENE, 1,3-DIMETHYL 108-38-3	4.9: 72 h Pseudokirchneriella subcapitata mg/L EC50 static	14.3 - 18: 96 h Pimephales promelas mg/L LC50 flow-through 8.4: 96 h Oncorhynchus mykiss mg/L LC50 semi-static 12.9: 96 h Poecilia reticulata mg/L LC50 semi-static	2.81 - 5.0: 48 h Daphnia magna mg/L EC50 Static

Persistence and degradability

No information available.

Bioaccumulation

No information available.

Mobility in Environmental Media

Chemical name	log Pow
XYLENE	2.77
1330-20-7	
BENZYL ALCOHOL	1.1
100-51-6	
N-BUTANOL (SKIN)	0.785
71-36-3	
ETHYL BENZENE	3.118
100-41-4	
ISOPHORONE DIAMINE	0.79
2855-13-2	
BENZENE, 1,3-DIMETHYL	3.2
108-38-3	

Other Adverse Effects

No information available

13. DISPOSAL CONSIDERATIONS

Waste treatment methods

Disposal Methods Keep container tightly closed. If spilled, contain spilled material and remove with inert

absorbent. Dispose of contaminated absorbent, container and unused contents in

accordance with local, state and federal regulations.

Contaminated packaging Empty containers should be taken to an approved waste handling site for recycling or

disposal.

Chemical name	RCRA	RCRA - Basis for Listing	RCRA - D Series Wastes	RCRA - U Series Wastes
XYLENE		Included in waste stream:		U239
1330-20-7		F039		
N-BUTANOL (SKIN)		Included in waste stream:		U031
71-36-3		F039		
ETHYL BENZENE		Included in waste stream:		
100-41-4		F039		
FORMALDEHYDE	U122	Included in waste streams:		U122

50-00-0	K009, K010, K038, K040,	
	K156, K157	

Chemical name	CAWAST
XYLENE	Toxic
1330-20-7	Ignitable
N-BUTANOL (SKIN)	Toxic
71-36-3	
ETHYL BENZENE	Toxic
100-41-4	Ignitable

14. TRANSPORT INFORMATION

DOT

UN/ID no. 1263
Proper Shipping Name PAINT
Hazard Class 3
Packing Group III
Emergency Response Guide 128

Number

<u>Additional information</u> Call TNEMEC Traffic Department - 816-474-3400 for additional information or other modes

of Transportation.

15. REGULATORY INFORMATION

International Inventories

TSCA Complies **DSL/NDSL** Complies **EINECS/ELINCS** Complies **ENCS** Complies Complies **IECSC** Does Not Comply **KECL** Complies **PICCS** Does Not Comply **AICS**

TSCA - United States Toxic Substances Control Act Section 8(b) Inventory

DSL/NDSL - Canadian Domestic Substances List/Non-Domestic Substances List

EINECS/ELINCS - European Inventory of Existing Commercial Chemical Substances/EU List of Notified Chemical Substances

ENCS - Japan Existing and New Chemical Substances

IECSC - China Inventory of Existing Chemical Substances

KECL - Korean Existing and Evaluated Chemical Substances

PICCS - Philippines Inventory of Chemicals and Chemical Substances

AICS - Australian Inventory of Chemical Substances

The following chemical(s) are listed as HAP under the U.S. Clean Air Act, Section 12 (40 CFR 61):

Chemical name HAPS Data

XYLENE ETHYL BENZENE BENZENE, 1,3-DIMETHYL

SARA 313

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA). This product contains a chemical or chemicals which are subject to the reporting requirements of the Act and and Title 40n of the Code of Federal Regulations, Part 372:

Chemical name	SARA 313 - Threshold Values
BARIUM SULFATE (TOTAL DUST) - 7727-43-7	1.0
XYLENE - 1330-20-7	1.0
N-BUTANOL (SKIN) - 71-36-3	1.0

ETHYL BENZENE - 100-41-4	0.1
BENZENE, 1,3-DIMETHYL - 108-38-3	1.0

SARA 311/312 Hazardous

Categorization

Acute Health Hazard Yes
Chronic Health Hazard Yes
Fire Hazard Yes
Sudden Release of Pressure Hazard No
Reactive Hazard No

Chemical name	CWA - Reportable Quantities	CWA - Toxic Pollutants	CWA - Priority Pollutants	CWA - Hazardous Substances
XYLENE 1330-20-7	100 lb			Х
ETHYL BENZENE 100-41-4	1000 lb	X	X	X
BENZENE, 1,3-DIMETHYL 108-38-3				X

Chemical name	Hazardous Substances RQs	CERCLA EHS RQs	RQ
XYLENE	100 lb		RQ 100 lb final RQ
1330-20-7			RQ 45.4 kg final RQ
N-BUTANOL (SKIN)	5000 lb		RQ 5000 lb final RQ
71-36-3			RQ 2270 kg final RQ
ETHYL BENZENE	1000 lb		RQ 1000 lb final RQ
100-41-4			RQ 454 kg final RQ
BENZENE, 1,3-DIMETHYL	1000 lb		RQ 1000 lb final RQ
108-38-3			RQ 454 kg final RQ

California Prop. 65

WARNING: This product can expose you to the following chemicals which are known to the State of California to cause cancer. For more information go to www.P65Warnings.ca.gov.

Chemical name	California Prop. 65	
ETHYL BENZENE - 100-41-4	Carcinogen	
P-P'-ISOPROPYLIDENEDIPHENOL - 80-05-7	Female Reproductive	
FORMALDEHYDE - 50-00-0	Carcinogen	
CRYSTALLINE SILICA (QUARTZ) - 14808-60-7	Carcinogen	

California SCAQMD Rule 443

Contains Photochemically Reactive Solvent

State Right-to-Know

Chemical name	New Jersey	Massachusetts	Pennsylvania
BARIUM SULFATE (TOTAL DUST) 7727-43-7	Х	Х	X
MAGNESIUM SILICATE	Х	Х	Х
XYLENE 1330-20-7	Х	X	Х
BENZYL ALCOHOL 100-51-6		Х	Х
N-BUTANOL (SKIN) 71-36-3	X	X	X
ETHYL BENZENE 100-41-4	X	X	Х
ISOPHORONE DIAMINE 2855-13-2	Х		
BENZENE, 1,3-DIMETHYL 108-38-3	Х	X	X

16. OTHER INFORMATION

Reactivity 1

NFPA Health 2 Flammability 3 Instability 1 Physical hazard * Flammability 3

HMIS (Hazardous Health 2* **Material Information**

System)

Prepared By Tnemec Regulatory Dept: 816-474-3400

Issue Date 23-May-2017 13-Mar-2020 **Revision Date**

Revision Summary 9 4 5 7 10 8 2 11 14 1

Disclaimer

For specific information regarding occupational safety and health standards, please refer to the Code of Federal Regulations, Title 29, Part 1910.

To the best of our knowledge, the information contained herein is accurate. However, neither the Tnemec Company or any of its subsidiaries assume any liability whatsoever for the accuracy of completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown health hazards and should be used with caution. Although certain hazards are described herein, we cannot quarantee that these are the only hazards which exist.

End of SDS